

# **Annual Inspection**

Barby & Onley Parish Council

Barby Play Area

Daventry Road, Barby, CV23 8TT







Wicksteed Leisure Limited, Digby Street, Kettering, Northamptonshire, NN16 8YJ

www.wicksteed.co.uk

01536 517028 customerservices@wicksteed.co.uk



# **Inspection Scope for RPII Inspection Methodology**

This document outlines the RPII scope for inspections undertaken by the Inspectors listed as Annual Inspectors on the RPII Register of Inspectors when undertaking Indoor Annual, Outdoor Annual, Outdoor Operational and Outdoor Routine inspections.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it will be the standard that is current at the time of inspection except where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection, unless they are also explicitly listed here.

The following standards are relevant to all installations of equipment that are publicly accessible to users; this includes public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below):

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, excluding ancillary items).

In the United Kingdom the National Foreword forms an important part to the understanding and implementation of the recommendations set out in this document. It clarifies the application of the document within the UK as best practice guidance, as the document has been used since its initial publication. Therefore, in the UK this standard (BS EN 1176 – Part 7) contains no requirements and needs to be read and implemented as guidance, with the use of the term 'shall' therefore becoming a recommendation, as in the term 'should'.

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standards (BS EN 71 series – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report but any comments concerning compliance will follow the requirements and recommendations of BS EN 1176.

When water play items, including spray parks, are inspected any comments concerning compliance within the inspection will refer to BS EN 1176. We have not assessed these against the requirements of BS EN 17232 (Water play equipment and features).

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

- BS EN 15312 Free access multi-sports equipment
- BS EN 14974 Skateparks
- BS EN 16630 Permanently installed outdoor fitness equipment
- BS EN 16899 Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with these current standards, and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area (that area which is obviously part of the playground), nominally up to three metres around, the fence line if closer, or other areas as agreed.

Operational inspections only take into consideration defects related to cleanliness, equipment ground clearances, ground surface finishes, exposed foundations, sharp edges, missing parts, excessive wear (of moving parts) structural integrity, wear and vandalism.

Routine visual inspections relate only to the most obvious defects such as broken or missing parts, litter, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

All inspections are non-dismantling, non-destructive and do not include any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a manual test for stability and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all reasonably accessible equipment and will assess all reasonably accessible parts above the standing surface. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment.

Ancillary equipment will be assessed using the inspector's knowledge and experience of the standards named in this document. (Note: Ancillary items are not included in the specific equipment-type parts of the EN 1176 series; hence they are not assessed for compliance with EN 1176 series and are subject to a general safety assessment).

The owner/operator is responsible for the overall safety of the equipment and area.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of the impact attenuating properties of any surfaces; the identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection; the inspection of any equipment (or part thereof) that is beneath the playing surface (loose-fill materials may be moved to expose foundations); tightening any bolts, hinges or other fixing devices on any apparatus or equipment; assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment; assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming); where planting or trees are mentioned in the report no assessments of toxicity, suitability or condition are undertaken – the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a 'design risk assessment' provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a 'suitable and sufficient assessment' of the risks associated with a site or activity. This inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/or that of the inspection company. The owner/operator should always seek the advice of the manufacturer or a competent person when undertaking repairs and/or modifications to equipment.

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection recommendations of relevant standards Refer to relevant standards for full text	Annual Main	RPII Annual/ Post Installation Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	~	✓ [1]
6.1 d) Overall levels of safety of foundations (see note 1)	<ul> <li></li> </ul>	✓ [1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	~	✓ [2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	~	✓ [3]
6.1 d) Effects of weather	<ul> <li></li> </ul>	~
6.1 d) Presence of rot, decay or corrosion (see note 1)	$\checkmark$	✓ [1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	<ul> <li></li> </ul>	✓ [4]
6.1 d) Excavation or dismantling/additional measures	<ul> <li></li> </ul>	×
6.2.1 Assessment of glass reinforced plastics (see note 5)	$\checkmark$	✓ [5]
6.2.1 Inspection of one post equipment (see note 1)	<ul> <li></li> </ul>	✓ [1]
6.2.4 Undertaking the Operators inspection protocol	$\checkmark$	×

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant standards.

[1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.

[2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.

[3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.

[4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance.

[5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

© The Play Inspection Company & the Register of Play Inspectors International 15th September 2021

# **Risk Assessment Matrix**

			Scores in	n the report a	are multiplica	ation factors	of Likelihood	x Severity
			Severity>>					
	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)
Likelihood	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)
			L	Very Low	Low	Moderate	High	Very High
				1	2	3	4	5
	• SNCE 1918 -             • SNCE 1918 -             No injury likely         • g. damaged         • SNCE 1918 -             No injury likely         • g. damaged         • SNCE 1918 -             No injury likely         • g. damaged         • SNCE 1918 -             No injury likely         • g. damaged         • solled         • clothing, minor         grazes             Minor injury,         laceration or         pointsing         requiring first         aid only         stitches             Serious injury              <							
						Severity>>		
each finding numbers are	total risk scores included within b. Both Likelihood and Severity e then multiplied together to give led in both directions, i.e. a total	are ve t	e given a num he total risk s	ber between core that is s	1 - 5 as shov hown against	vn on the mat defects on th	rix above and the report. Total	these two risk scores
Note 2: Whe	en we inspect we only see a sr	naps	shot of the cu	irrent conditio	n of the equi	oment. It is th	e operators res	sponsibility to

Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.



# Barby Play Area

Inspection Ref: 1697810

Site Ref: 90997

Customer Order: 1259812 / 418785

Inspected: 28-June-2022 - 12:00 by Jim Hayes

Risk Assessment: 16 High Risk



### Location:

The site is located in an area of public open space and is overlooked by a number of properties in the local community. **Disabled Access:** 

Generally accessible; an area accessible to most.



16 - High Risk		
Item: Manufacturer: Surface Type: Item Quantity: Equipment Compliance: Surface Area Compliance: Total Findings:	1 Bay 2 Seat (Cradle) Unknown Bark Mulch 1 N/A N/A	
Finding 1		Finding 2
The seat is severely damage Replace damaged seat	ed and requires replacing -	The bushes are worn or missing - Replace worn or missing bushes
Finding 3		Finding 4
The chain links are worn in e renewing - Replace worn cha		The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability
Finding 5		]
	growth between or around the nove weeds/vegetation growth	



8 - Low Risk		
Item:	Spring Bike	
Manufacturer:	Wicksteed Playgrounds	
Surface Type:	Bark Mulch	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	3	
Finding 1		Finding 2
The surface has eroded and Reinstate surrounding surface	the foundations are exposed - ces to cover the foundations	The item is slightly loose in its foundations - Monitor for any further deterioration and repair as required
Finding 3		
	footrests have a cross section	
	o meet the requirements of BS	
EN 1176 Part 6 - Monitor - N	o remedial work recommended	
8 - Low Risk		
Item:	Multi Play (Toddler)	
Manufacturer:	Sovereign Leisure	
Surface Type:	Bark Mulch	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	

Total Findings:

### Finding 1

The surface has eroded and the foundations are exposed - Reinstate surrounding surfaces to cover the foundations

1



8 - Low Risk		
Item:	Ship	
Manufacturer:	Sovereign Leisure	
Surface Type:	Bark Mulch	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
-		
Total Findings:	3	
Finding 1		Finding 2
	the foundations are exposed -	There are weeds/vegetation growth between or around the
Reinstate surrounding surface		edges of the surfacing - Remove weeds/vegetation growth
Finding 3		
	ot in the timber - Monitor for any	
further deterioration and repl		
8 - Low Risk		
Item:	Roundabout	
Manufacturer:	Unknown	
Surface Type:	EcoScape Softbond	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Cindinana.	2	
Total Findings:	3	
Total Findings:	3	
	3	Finding 2
Finding 1		Finding 2 The item has been damaged - Monitor for any further
<b>Finding 1</b> The item is slightly loose in i	ts foundations or the bearings	Finding 2 The item has been damaged - Monitor for any further deterioration and replace as required
Finding 1	ts foundations or the bearings	The item has been damaged - Monitor for any further
<b>Finding 1</b> The item is slightly loose in i may be worn - Monitor for ar repair as required	ts foundations or the bearings	The item has been damaged - Monitor for any further
Finding 1 The item is slightly loose in ir may be worn - Monitor for ar repair as required Finding 3	ts foundations or the bearings	The item has been damaged - Monitor for any further
Finding 1 The item is slightly loose in it may be worn - Monitor for ar repair as required Finding 3 There are weeds/vegetation	ts foundations or the bearings ny further deterioration and	The item has been damaged - Monitor for any further



6 - Low Risk		
Item: Manufacturer: Surface Type: Item Quantity: Equipment Compliance: Surface Area Compliance: Total Findings:	Pull Up Station Unknown Grass 1 N/A N/A 2	
Finding 1		Finding 2
The surface has eroded in so surface	ome areas - Reinstate the	The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability
6 - Low Risk		
Item: Manufacturer: Surface Type: Item Quantity: Equipment Compliance: Surface Area Compliance: Total Findings:	Trapeze Rings Unknown Grass Matrix Tiles 1 N/A N/A 3	
Finding 1		Finding 2
The item is slightly loose in it further deterioration and repared Finding 3		1 grass mat is missing - Replace

The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability



6 - Low Risk		
Item: Manufacturer: Surface Type: Item Quantity: Equipment Compliance: Surface Area Compliance: Total Findings:	Log Climber Unknown Grass 1 N/A N/A 3	
Finding 1		Finding 2
There is/are bolt cap covers item - Replace missing or da		The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability
Finding 3		
the posts, this can penetrate	Ichinery damage apparent on the preservative applied to the tting process - Monitor for any e as required	
Item: Manufacturer: Surface Type: Item Quantity: Equipment Compliance: Surface Area Compliance:	Bridge Unknown Grass 1 N/A N/A	
Total Findings:	2	Lattetter V
Finding 1		Finding 2
There is/are bolt cap covers item - Replace missing or da		The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability



Item: Monufacturer	Misc Item	
Manufacturer: Surface Type:	Unknown Grass	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance: Total Findings:	N/A 2	
Finding 1		Finding 2
the posts, this can penetrate	chinery damage apparent on the preservative applied to the tting process - Monitor for any e as required	There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required

# 😭 10 - Low Risk

**Total Findings:** 

Item:	2 Bay 2 Flat 1 Basket Seat
Manufacturer:	Unknown
Surface Type:	Grass Matrix Tiles
Item Quantity:	1
Equipment Compliance:	N/A
Surface Area Compliance:	N/A

3

 Finding 1
 Finding 2

 The edges of the grass mat surface have not been installed in accordance with the API Code of Practice - Tuck in edges of grass mat to remove trip hazards
 Large dips in the playing surface - Rework

 Finding 3
 Finding 1

The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability



# 6 - Low Risk Item: Free Standing Slide Manufacturer: Play & Leisure Ltd Surface Type: Grass Matrix Tiles Item Quantity: 1 Equipment Compliance: N/A Surface Area Compliance: N/A Total Findings: 1

### Finding 1

The slide is predominately south facing and will catch the majority of the sun's heat during the day. Slide surfaces can become very warm during periods of sustained sunny weather - Monitor - No remedial work recommended

6 - Low Risk	

Football Goal	
Unknown	
Grass	
2	
N/A	
N/A	
3	
	Finding 2
ome areas - Reinstate the	The item is slightly loose in its foundations - Monitor for any further deterioration and repair as required
	]
resent on the item - Consider	-
	Unknown Grass 2 N/A N/A 3 3



Item:	Goalmouth and Basketball Post	
Manufacturer:	SMP	APENA APENA
Surface Type:	Tarmac	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	1	

The item has been damaged - Monitor for any further deterioration and replace as required

tem:	Seat	
Manufacturer:	Unknown	
Surface Type:	Concrete	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	1	



# 😭 2 - Very Low Risk

Item: Manufacturer: Surface Type: Grass Item Quantity: 1 **Equipment Compliance:** N/A Surface Area Compliance: N/A

Total Findings:





### Finding 1

There is no liner present in the litter bin - Provide as required

1

# 🗿 4 - Very Low Risk

Item:	Basketball Post	
Manufacturer:	Unknown	Odidos A
Surface Type:	Tarmac	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	1	
Finding 1		

This item is satisfactory - no work required -



6 - Low Risk		
Item:	Pull Down Challenger	
Manufacturer:	Sunshine Gym	
Surface Type:	Grass	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	2	
Finding 1		Finding 2
The surface has eroded in so surface	ome areas - Reinstate the	The item is slightly loose in its foundations - Monitor for any further deterioration and repair as required
4 - Very Low Risk		
Item:	Seat	
Manufacturer:	Unknown	
Surface Type:	Grass	
Item Quantity:	2	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	1	

# Finding 1

This item is satisfactory - no work required -




Item:	Site General	a market and a second
Manufacturer:	Unknown	
Surface Type:	Grass	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	1	

It is recommended that signage, with information including the site address, contact information for maintenance issues and emergency contact details are provided for the facility - Provide in accordance with the recommendations



# **Findings information**



Finding: The seat is severely damaged and requires replacing

Action: Replace damaged seat



# 8 - Low Risk (Finding 2) -Swings - 1 Bay 2 Seat (Cradle) Risk Level: L - Low Risk Item: Manufacturer: Unknown Surface: Bark Mulch Finding: The bushes are worn or missing Action: Replace worn or missing bushes 8 - Low Risk (Finding 3) Swings - 1 Bay 2 Seat (Cradle) Risk Level: L - Low Risk Item: Manufacturer: Unknown Surface: Bark Mulch

**Finding:** The chain links are worn in excess of 40% and require renewing

Action: Replace worn chains



# 6 - Low Risk (Finding 4) -Swings - 1 Bay 2 Seat (Cradle) Risk Level: L - Low Risk Item: Manufacturer: Unknown Surface: Bark Mulch **Finding:** The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability

which will accelerate the rotting process



### 6 - Low Risk (Finding 5) 4

Swings - 1 Bay 2 Seat (Cradle) Item: Unknown Manufacturer:

**Risk Level:** 

L - Low Risk Bark Mulch





Finding: There are weeds/vegetation growth between or around the edges of the surfacing

Action: Remove weeds/vegetation growth


# 8 - Low Risk (Finding 1) Item: Rocking Equipment - Spring Bike Risk Level: L - Low Risk Wicksteed Playgrounds Manufacturer: Surface: Bark Mulch Finding: The surface has eroded and the foundations are Action: Reinstate surrounding surfaces to cover the exposed foundations




# 6 - Low Risk (Finding 2) -Rocking Equipment - Spring Bike **Risk Level:** L - Low Risk Item: Wicksteed Playgrounds Bark Mulch Manufacturer: Surface: Finding: The item is slightly loose in its foundations Action: Monitor for any further deterioration and repair as required 6 - Low Risk (Finding 3) Item: Rocking Equipment - Spring Bike Risk Level: L - Low Risk Manufacturer: Wicksteed Playgrounds Surface: Bark Mulch

**Finding:** The end of handgrips and/or footrests have a cross **Action:** Monitor - No remedial work recommended section of less than 15cm2 and fail to meet the requirements of BS EN 1176 Part 6











**Finding:** There are weeds/vegetation growth between or around the edges of the surfacing

Action: Remove weeds/vegetation growth
















# 6 - Low Risk (Finding 2) Item: Outdoor Fitness Equipment - Pull Up Station Manufacturer: Unknown Surface: Grass

**Finding:** The timber has a number of splits/shakes or air **Action:** Monitor to ensure the splits do not cross through cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability which will accelerate the rotting process

# 6 - Low Risk (Finding 1)

 Item:
 Activity Equipment - Trapeze Rings
 Risk Level:
 L - Low Risk

 Manufacturer:
 Unknown
 Surface:
 Grass Matrix Tiles

Finding: The item is slightly loose in its foundations

Action: Monitor for any further deterioration and repair as required



### 6 - Low Risk (Finding 2)

Activity Equipment - Trapeze Rings Item: Manufacturer: Unknown

**Risk Level:** L - Low Risk Surface: Grass Matrix Tiles

Action: Replace

Finding: 1 grass mat is missing

6

# 6 - Low Risk (Finding 3)



Finding: The timber has a number of splits/shakes or air Action: Monitor to ensure the splits do not cross through cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability which will accelerate the rotting process




### 4 - Very Low Risk (Finding 1)

Item: Manufacturer:

Activity Equipment - Log Climber Unknown

**Risk Level:** Surface:

V - Very Low Risk Grass



Finding: There is/are bolt cap covers missing or damaged Action: Replace missing or damaged bolt cap covers on the item

# 6 - Low Risk (Finding 2)



Finding: The timber has a number of splits/shakes or air Action: Monitor to ensure the splits do not cross through cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability which will accelerate the rotting process



### 6 - Low Risk (Finding 3)

Item: Manufacturer:

Activity Equipment - Log Climber Unknown



**Finding:** There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process



Action: Monitor for any deterioration (rot) and replace as required


# 4 - Very Low Risk (Finding 1)

Item: Activity Equip Manufacturer: Unknown

Activity Equipment - Bridge

**Risk Level:** V - Very Low Risk **Surface:** Grass





Action: Replace missing or damaged bolt cap covers



# 6 - Low Risk (Finding 2) -Activity Equipment - Bridge **Risk Level:** L - Low Risk Item: Unknown Surface: Grass Manufacturer: Finding: The timber has a number of splits/shakes or air Action: Monitor to ensure the splits do not cross through cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability

which will accelerate the rotting process



# 6 - Low Risk (Finding 1)

Item: Manufacturer:

Other - Misc Item Unknown


**Risk Level:** Surface:

Risk Level:

L - Low Risk Grass



Finding: There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process



# 6 - Low Risk (Finding 2)

Item:

Other - Misc Item



Finding: There is some evidence of rot in the timber

L - Low Risk



Action: Monitor for any further deterioration and replace as required




-

Wicksteed Leisure Limited **Digby Street** Kettering Northamptonshire NN16 8YJ +44 (0)1536 517028

# 8 - Low Risk (Finding 1) Swings - 2 Bay 2 Flat 1 Basket Seat Risk Level: L - Low Risk Item: Manufacturer: Unknown Surface: **Grass Matrix Tiles**

Finding: The edges of the grass mat surface have not been Action: Tuck in edges of grass mat to remove trip hazards installed in accordance with the API Code of Practice







### 6 - Low Risk (Finding 3)

Item: Manufacturer: Swings - 2 Bay 2 Flat 1 Basket Seat Unknown Risk Level: Surface: L - Low Risk Grass Matrix Tiles



**Finding:** The timber has a number of splits/shakes or air **Action:** Monitor to ensure the splits do not cross through cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability which will accelerate the rotting process

**Risk Level:** 

# 6 - Low Risk (Finding 1)

Item: Manufacture Other - Free Standing Slide

Manufacturer: Play & Leisure Ltd



Surface: Grass Matrix Tiles

**Finding:** The slide is predominately south facing and will catch the majority of the sun's heat during the day. Slide surfaces can become very warm during periods of sustained sunny weather

Action: Monitor - No remedial work recommended

L - Low Risk











2 - Very Lo	ow Risk (Finding 1)		
Item: Manufacturer:	Ancillary Items - Litter Bin Unknown	Risk Level: Surface:	V - Very Low Risk Grass
Finding: There	is no liner present in the litter bin	Action: Provide	as required
6 - Low Ris	sk (Finding 1)		
Item:	Outdoor Fitness Equipment - Pull Down Challenger	Risk Level:	L - Low Risk
Manufacturer:	Sunshine Gym	Surface:	Grass



6 - Low Ris	sk (Finding 2)		
ltem: Manufacturer:	Outdoor Fitness Equipment - Pull Down Challenger Sunshine Gym	Risk Level: Surface:	L - Low Risk Grass
	m is slightly loose in its foundations	Action: Monitor required	for any further deterioration and repair as
Item: Manufacturer:	w Risk (Finding 1) Ancillary Items - Site General Unknown	Risk Level: Surface:	V - Very Low Risk Grass
Finding: It is real	commended that signage, with information		NO IMAGE APPLICABLE
	e address, contact information for		



# **Annual Inspection**

Barby & Onley Parish Council

Barby Skate Ramp

Longdown Lane, Barby, CV23 8TE







Wicksteed Leisure Limited, Digby Street, Kettering, Northamptonshire, NN16 8YJ

www.wicksteed.co.uk

01536 517028 customerservices@wicksteed.co.uk



# **Inspection Scope for RPII Inspection Methodology**

This document outlines the RPII scope for inspections undertaken by the Inspectors listed as Annual Inspectors on the RPII Register of Inspectors when undertaking Indoor Annual, Outdoor Annual, Outdoor Operational and Outdoor Routine inspections.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it will be the standard that is current at the time of inspection except where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection, unless they are also explicitly listed here.

The following standards are relevant to all installations of equipment that are publicly accessible to users; this includes public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below):

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, excluding ancillary items).

In the United Kingdom the National Foreword forms an important part to the understanding and implementation of the recommendations set out in this document. It clarifies the application of the document within the UK as best practice guidance, as the document has been used since its initial publication. Therefore, in the UK this standard (BS EN 1176 – Part 7) contains no requirements and needs to be read and implemented as guidance, with the use of the term 'shall' therefore becoming a recommendation, as in the term 'should'.

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standards (BS EN 71 series – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report but any comments concerning compliance will follow the requirements and recommendations of BS EN 1176.

When water play items, including spray parks, are inspected any comments concerning compliance within the inspection will refer to BS EN 1176. We have not assessed these against the requirements of BS EN 17232 (Water play equipment and features).

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

- BS EN 15312 Free access multi-sports equipment
- BS EN 14974 Skateparks
- BS EN 16630 Permanently installed outdoor fitness equipment
- BS EN 16899 Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with these current standards, and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area (that area which is obviously part of the playground), nominally up to three metres around, the fence line if closer, or other areas as agreed.

Operational inspections only take into consideration defects related to cleanliness, equipment ground clearances, ground surface finishes, exposed foundations, sharp edges, missing parts, excessive wear (of moving parts) structural integrity, wear and vandalism.

Routine visual inspections relate only to the most obvious defects such as broken or missing parts, litter, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

All inspections are non-dismantling, non-destructive and do not include any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a manual test for stability and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all reasonably accessible equipment and will assess all reasonably accessible parts above the standing surface. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment.

Ancillary equipment will be assessed using the inspector's knowledge and experience of the standards named in this document. (Note: Ancillary items are not included in the specific equipment-type parts of the EN 1176 series; hence they are not assessed for compliance with EN 1176 series and are subject to a general safety assessment).

The owner/operator is responsible for the overall safety of the equipment and area.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of the impact attenuating properties of any surfaces; the identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection; the inspection of any equipment (or part thereof) that is beneath the playing surface (loose-fill materials may be moved to expose foundations); tightening any bolts, hinges or other fixing devices on any apparatus or equipment; assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment; assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming); where planting or trees are mentioned in the report no assessments of toxicity, suitability or condition are undertaken – the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a 'design risk assessment' provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a 'suitable and sufficient assessment' of the risks associated with a site or activity. This inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/or that of the inspection company. The owner/operator should always seek the advice of the manufacturer or a competent person when undertaking repairs and/or modifications to equipment.

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection recommendations of relevant standards Refer to relevant standards for full text	Annual Main	RPII Annual/ Post Installation Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	~	✓ [1]
6.1 d) Overall levels of safety of foundations (see note 1)	<ul> <li></li> </ul>	✓ [1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	~	✓ [2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	~	✓ [3]
6.1 d) Effects of weather	<ul> <li></li> </ul>	~
6.1 d) Presence of rot, decay or corrosion (see note 1)	$\checkmark$	✓ [1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	<ul> <li></li> </ul>	✓ [4]
6.1 d) Excavation or dismantling/additional measures	<ul> <li></li> </ul>	×
6.2.1 Assessment of glass reinforced plastics (see note 5)	$\checkmark$	✓ [5]
6.2.1 Inspection of one post equipment (see note 1)	<ul> <li></li> </ul>	✓ [1]
6.2.4 Undertaking the Operators inspection protocol	$\checkmark$	×

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant standards.

[1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.

[2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.

[3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.

[4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance.

[5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

© The Play Inspection Company & the Register of Play Inspectors International 15th September 2021

# **Risk Assessment Matrix**

			Scores in	n the report a	are multiplica	ation factors	of Likelihood	x Severity
					Sev	erity>>		
	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)
Likelihood	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)
			L	Very Low	Low	Moderate	High	Very High
				1	2	3	4	5
e.g. damaged or soiled laceration or bruising						Severe injury involving a potential life changing injury or fatality		
	Severity>>							
Note 1: The total risk scores included within our reports are a multiplication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity								
(3). Note 2: Whe	en we inspect we only see a sr	naps	shot of the cu	irrent conditio	n of the equi	oment. It is th	e operators res	sponsibility to

Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.



# Barby Skate Ramp

Inspection Ref: 1697809

Site Ref: 90998

Customer Order: 1259812 / 418785

Inspected: 28-June-2022 - 11:41 by Jim Hayes

Risk Assessment: 6 Low Risk



#### Location:

The site is located in an area of public open space and is not directly overlooked by any properties in the local community.

#### Disabled Access:

Generally accessible; an area accessible to most.



# Item: Half Pipe Manufacturer: Unknown Surface Type: Concrete Item Quantity: 1 Equipment Compliance: N/A Surface Area Compliance: N/A Total Findings: 1


#### Finding 1

Signage of the wheeled sports area should be provided as recommended in BS EN 14974; this will include,a) facility for users of skateboards, inline-skates and BMX bikes (with site name or information); b) administrator's identification with telephone number of the maintenance personnel and general emergency number; c) the facility is not a playground, its use is for adults, teenagers and children above the age of 8; d) the use of unsuitable equipment such as traditional road bikes, motorised sports equipment or toys is not permitted; e) use of appropriate protective equipment (e.g. helmet, knee pads, elbow pads, etc.) is recommended; f) pay attention to other users; g) the rolling surfaces and skate elements are not a waiting area and shall be kept clear of objects; h) the facility shall not be used when wet, icy or in snow conditions. - Provide signage as recommended by BS EN 14974 for wheeled sports areas

6 - Low Risk		
Item:	Gate	
Manufacturer:	Unknown	
Surface Type:	Grass	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	1	
Finding 1		
The adjacent foliage is overh	anging - Cut back and maintain	



### **Findings information**







Finding: The adjacent foliage is overhanging

Action: Cut back and maintain



# **Annual Inspection**

Barby & Onley Parish Council

Onley Play Area

89 Onley Park, Onley, Wiloughby, CV23 8AN







Wicksteed Leisure Limited, Digby Street, Kettering, Northamptonshire, NN16 8YJ

www.wicksteed.co.uk

01536 517028 customerservices@wicksteed.co.uk



# **Inspection Scope for RPII Inspection Methodology**

This document outlines the RPII scope for inspections undertaken by the Inspectors listed as Annual Inspectors on the RPII Register of Inspectors when undertaking Indoor Annual, Outdoor Annual, Outdoor Operational and Outdoor Routine inspections.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it will be the standard that is current at the time of inspection except where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection, unless they are also explicitly listed here.

The following standards are relevant to all installations of equipment that are publicly accessible to users; this includes public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below):

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, excluding ancillary items).

In the United Kingdom the National Foreword forms an important part to the understanding and implementation of the recommendations set out in this document. It clarifies the application of the document within the UK as best practice guidance, as the document has been used since its initial publication. Therefore, in the UK this standard (BS EN 1176 – Part 7) contains no requirements and needs to be read and implemented as guidance, with the use of the term 'shall' therefore becoming a recommendation, as in the term 'should'.

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standards (BS EN 71 series – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report but any comments concerning compliance will follow the requirements and recommendations of BS EN 1176.

When water play items, including spray parks, are inspected any comments concerning compliance within the inspection will refer to BS EN 1176. We have not assessed these against the requirements of BS EN 17232 (Water play equipment and features).

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

- BS EN 15312 Free access multi-sports equipment
- BS EN 14974 Skateparks
- BS EN 16630 Permanently installed outdoor fitness equipment
- BS EN 16899 Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with these current standards, and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area (that area which is obviously part of the playground), nominally up to three metres around, the fence line if closer, or other areas as agreed.

Operational inspections only take into consideration defects related to cleanliness, equipment ground clearances, ground surface finishes, exposed foundations, sharp edges, missing parts, excessive wear (of moving parts) structural integrity, wear and vandalism.

Routine visual inspections relate only to the most obvious defects such as broken or missing parts, litter, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

All inspections are non-dismantling, non-destructive and do not include any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a manual test for stability and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all reasonably accessible equipment and will assess all reasonably accessible parts above the standing surface. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment.

Ancillary equipment will be assessed using the inspector's knowledge and experience of the standards named in this document. (Note: Ancillary items are not included in the specific equipment-type parts of the EN 1176 series; hence they are not assessed for compliance with EN 1176 series and are subject to a general safety assessment).

The owner/operator is responsible for the overall safety of the equipment and area.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of the impact attenuating properties of any surfaces; the identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection; the inspection of any equipment (or part thereof) that is beneath the playing surface (loose-fill materials may be moved to expose foundations); tightening any bolts, hinges or other fixing devices on any apparatus or equipment; assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment; assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming); where planting or trees are mentioned in the report no assessments of toxicity, suitability or condition are undertaken – the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a 'design risk assessment' provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a 'suitable and sufficient assessment' of the risks associated with a site or activity. This inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/or that of the inspection company. The owner/operator should always seek the advice of the manufacturer or a competent person when undertaking repairs and/or modifications to equipment.

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection recommendations of relevant standards Refer to relevant standards for full text	Annual Main	RPII Annual/ Post Installation Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	~	✓ [1]
6.1 d) Overall levels of safety of foundations (see note 1)	<ul> <li></li> </ul>	✓ [1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	~	✓ [2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	~	✓ [3]
6.1 d) Effects of weather	<ul> <li></li> </ul>	~
6.1 d) Presence of rot, decay or corrosion (see note 1)	$\checkmark$	✓ [1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	<ul> <li></li> </ul>	✓ [4]
6.1 d) Excavation or dismantling/additional measures	<ul> <li></li> </ul>	×
6.2.1 Assessment of glass reinforced plastics (see note 5)	$\checkmark$	✓ [5]
6.2.1 Inspection of one post equipment (see note 1)	<ul> <li></li> </ul>	✓ [1]
6.2.4 Undertaking the Operators inspection protocol	$\checkmark$	×

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant standards.

[1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.

[2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.

[3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.

[4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance.

[5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

© The Play Inspection Company & the Register of Play Inspectors International 15th September 2021

# **Risk Assessment Matrix**

			Scores in	n the report a	are multiplica	ation factors	of Likelihood	x Severity
					Sev	erity>>		
	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)
Likelihood	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)
			L	Very Low	Low	Moderate	High	Very High
				1	2	3	4	5
e.g. damaged or soiled laceration or bruising						Severe injury involving a potential life changing injury or fatality		
	Severity>>							
Note 1: The total risk scores included within our reports are a multiplication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity								
(3). Note 2: Whe	en we inspect we only see a sr	naps	shot of the cu	irrent conditio	n of the equi	oment. It is th	e operators res	sponsibility to

Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.



# **Onley Play Area**

Inspection Ref: 1697811

Site Ref: 90999

Customer Order: 1259812 / 418785

Inspected: 28-June-2022 - 13:16 by Jim Hayes

Risk Assessment: 12 Moderate Risk



#### Location:

The site is located in an area of public open space and is overlooked by a number of properties in the local community. **Disabled Access:** 

Generally accessible; an area accessible to most.



#### 👔 6 - Low Risk

—	
Item:	1 Ba
Manufacturer:	Play
Surface Type:	Gra
Item Quantity:	1
Equipment Compliance:	N/A
Surface Area Compliance:	N/A

1 Bay 1 Seat (Cradle) - Type 1 Playdale Playgrounds Ltd Grass Matrix Tiles 1 N/A N/A

Total Findings:



# Finding 1 Finding 2 The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required Finding 3 There is some notable evidence of chain wear - Monitor for

any further deterioration and replace when 40% worn

3

9 - Low Risk		
Item:	Multi Play (Junior)	
Manufacturer:	Playdale Playgrounds Ltd	
Surface Type:	Grass Matrix Tiles	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	4	
Finding 1		Finding 2
There are gaps opening betw Reinstate surface	veen the grass mat tiles -	The slide is predominately south facing and will catch the majority of the sun's heat during the day. Slide surfaces can become very warm during periods of sustained sunny weather - Monitor - No remedial work recommended
Finding 3		Finding 4
The rope has worn and wire rope or net	strands are exposed - Replace	The xxx forms a hard object within the falling space of the equipment in contravention of the requirements of BS EN 1176 Part 1 - Monitor - No remedial work recommended



Item:	1 Bay 2 Seat (Flat)	
Manufacturer:	Unknown	
Surface Type:	Grass Matrix Tiles	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	1	

#### 4 - Very Low Risk

Item: Manufacturer: Surface Type: Item Quantity: Equipment Compliance: Surface Area Compliance:	Climbing Frame Wicksteed Playgrounds Grass Matrix Tiles 1 N/A	
Total Findings:	1	La particular

This item is satisfactory - no work required -



4 - Very Low Risk		
Item:	Rotating Net	
Manufacturer:	Tayplay Ltd	。 一個的語名語等。 一個的語名語。 一個的語。 一個的語。 一個的語。 一個的語。 一個的語。 一個的語。 一個的語。 一個的語言。 一個的語: 一個的語: 一個的語: 一個的語: 一個的語: 一個的語: 一個的語: 一個的語: 一個的語: 一個的語: 一個的語: 一個的一個 一個語: 一個的一個 一個 一個 一個 一個 一個 一個 一個 一個 一個 一個 一個 一個 一
Surface Type:	Grass Matrix Tiles	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	: N/A	
Total Findings:	1	
Finding 1		
This item is satisfactory - no	work required -	
4 - Very Low Risk		
Item:	Seat	
Manufacturer:	Unknown	
Surface Type:	Grass	
Item Quantity:	1	
Equipment Compliance:	N/A	

Surface Area Compliance: N/A **Total Findings:** 

#### Finding 1

This item is satisfactory - no work required -

1



Equipment Compliance:

**Total Findings:** 

Finding 1

Surface Area Compliance: N/A

This item is satisfactory - no work required -

N/A

1

Item:	Spring Horse	
Manufacturer:	Ausplay	
Surface Type:	Grass	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance	: N/A	
Total Findings:	1	
Finding 1		
This item is satisfactory - no	o work required -	
1113 11611 13 Satisfactory - 110		
4 - Very Low Risk		
4 - Very Low Risk	Misc Springer	
	Misc Springer Ausplay	
4 - Very Low Risk		



Item:	Spring Duck	
Manufacturer:	Ausplay	
Surface Type:	Grass	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	1	
Finding 1		
This item is satisfactory - no	work required -	

4 - Very Low Risk
4 - VELY LOW RISK

tem:	Fencing - Timber	
lanufacturer:	Unknown	
Surface Type:	Grass	The second secon
tem Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
otal Findings:	1	

This item is satisfactory - no work required -




6 - Low Risk		
Item:	Gate	
Manufacturer:	Unknown	
Surface Type:	Mixed Surface	
Item Quantity:	1	
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	
Total Findings:	2	
Finding 1		Finding 2
The spring has detached - Refix		There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required
0 - Risk Assessment no	ot Undertaken Playground Sign	
Manufacturer:	Unknown	
Surface Type:	N/A	
Item Quantity:	1	ONLEY PARK PLAY AREA
Equipment Compliance:	N/A	
Surface Area Compliance:	N/A	This Play Area has been provided by Barby & Onley
ounace Area compliance.		Partish Council for children of up to 14 years of age. To report any incidents or damage occurring within the play area, please contact the Parish Clerk at clerk@batryandelyspartishcouncil.c.auk
Total Findings:	1	ClearEquilibrium Clear C

#### Finding 1

The emergency contact number should be 999 or 112 - Change the number on the sign



# **Findings information**





#### 6 - Low Risk (Finding 3)

Item: Manufacturer:

Swings - 1 Bay 1 Seat (Cradle) - Type 1 Playdale Playgrounds Ltd


Risk Level: Surface:

L - Low Risk Grass Matrix Tiles



Finding: There is some notable evidence of chain wear

Action: Monitor for any further deterioration and replace when 40% worn



Finding: There are gaps opening between the grass mat tiles

Action: Reinstate surface




#### 6 - Low Risk (Finding 2) 4

Activity Equipment - Multi Play (Junior) **Risk Level:** L - Low Risk Item: Manufacturer: Playdale Playgrounds Ltd Surface: Grass Matrix Tiles 


Finding: The slide is predominately south facing and will catch the majority of the sun's heat during the day. Slide surfaces can become very warm during periods of sustained sunny weather

Action: Monitor - No remedial work recommended









**Finding:** The xxx forms a hard object within the falling space of the equipment in contravention of the requirements of BS EN 1176 Part 1







